




Lathe Chart
(Cone Head)

- | | |
|----------------------------|--|
| 1 Cabinet legs | 28 Front bed leg |
| 2 Chip pan | 29 Reverse rod |
| 3 Rear bed leg | 29A Reverse rod bell crank |
| 4 Lathe bed | 30 Apron reverse lever |
| 5 Ways of bed | 31 Cross feed knob |
| 6 Head stock | 32 Rack pinion eccentric lever |
| 7 Tail stock top | 33 Apron hand wheel |
| 8 Tail stock base | 34 Longitudinal feed knob |
| 9 Apron | 35 Lead screw |
| 10 Carriage | 36 Lead screw half nuts lever |
| 11 Main feed gear box | 37 Micrometer carriage stop |
| 12 3-speed outer gear box | 38 Tail stock binding lever |
| 13 Headstock cone | 38A Tail stock hand wheel |
| 14 Gear guards | 39 Tail stock barrel cap |
| 15 Back gear lever | 40 Tail stock spindle |
| 16 Feed gear lever | 41 Tail stock center |
| 17 Oil hole cups | 42 Tail stock spindle binding lever |
| 18 Spindle bearing collar | 43 Taper attachment setting knob |
| 19 Driving plate | 44 Comp. rest slide |
| 20 Head center | 45 Comp. rest feed crank |
| 21 Speed gear change lever | 46 Cross slide and taper attachment binder |
| 22 Feed gear change lever | 47 Tool post |
| 23 Thread index | 48 Tool post collar |
| 24 Tool pin | 49 Cross feed screw handle |
| 25 Automatic stop rod | 50 Threading stop rod |
| 26 Stop rod stops | 51 Taper attachment binding bolt |
| 27 Adjustable feed stop | |